



Honda OBD I vehicles (1985 - 1995) supported by Actron's Honda/Nissan/Toyota Code Scanner CP9025

Year	Make	Model	Engine	Special	Covered By
1985	Honda	Accord SEi	1.8 L, 4 Cyl, ES3		CP9025
1985	Honda	Civic CRX Si	1.5 L, 4 Cyl, EW3		CP9025
1986	Honda	Accord LXi	2.0 L, 4 Cyl, BT		CP9025
1986	Honda	Civic CRX Si	1.5 L, 4 Cyl, EW3		CP9025
1986	Honda	Civic Si	1.5 L, 4 Cyl, EW3		CP9025
1986	Honda	Prelude	2.0 L, 4 Cyl, BT		CP9025
1987	Honda	Accord LXi	2.0 L, 4 Cyl, A20A3		CP9025
1987	Honda	Civic CRX Si	1.5 L, 4 Cyl, D15A3		CP9025
1987	Honda	Civic Si	1.5 L, 4 Cyl, D15A3		CP9025
1987	Honda	Prelude	2.0 L, 4 Cyl, A20A3		CP9025
1988	Honda	Accord LXi	2.0 L, 4 Cyl, A20A3		CP9025
1988	Honda	Civic CRX	1.5 L, 4 Cyl, D15B6		CP9025
1988	Honda	Civic CRX	1.5 L, 4 Cyl, D15B2		CP9025
1988	Honda	Civic CRX	1.6 L, 4 Cyl, D16A6		CP9025
1988	Honda	Civic	1.5 L, 4 Cyl, D15B1		CP9025
1988	Honda	Civic	1.5 L, 4 Cyl, D15B2		CP9025
1988	Honda	Civic Wagon	1.5 L, 4 Cyl, D15B2		CP9025
1988	Honda	Civic Wagon	1.6 L, 4 Cyl, D16A6		CP9025
1988	Honda	Prelude	2.0 L, 4 Cyl, B20A3		CP9025
1988	Honda	Prelude	2.0 L, 4 Cyl, B20A5		CP9025
1989	Honda	Accord LXi	2.0 L, 4 Cyl, A20A3		CP9025
1989	Honda	Civic CRX	1.5 L, 4 Cyl, D15B6		CP9025
1989	Honda	Civic CRX	1.5 L, 4 Cyl, D15B2		CP9025
1989	Honda	Civic CRX	1.6 L, 4 Cyl, D16A6		CP9025
1989	Honda	Civic	1.5 L, 4 Cyl, D15B6		CP9025
1989	Honda	Civic	1.5 L, 4 Cyl, D15B2		CP9025
1989	Honda	Civic	1.6 L, 4 Cyl, D16A6		CP9025
1989	Honda	Civic Wagon	1.5 L, 4 Cyl, D15B6		CP9025
1989	Honda	Civic Wagon	1.5 L, 4 Cyl, D15B2		CP9025
1989	Honda	Civic Wagon	1.6 L, 4 Cyl, D16A6		CP9025
1989	Honda	Prelude	2.0 L, 4 Cyl, B20A3		CP9025
1989	Honda	Prelude	2.0 L, 4 Cyl, B20A5		CP9025
1990	Honda	All	All		CP9025
1991	Honda	All	All		CP9025
1992	Honda	All	All		CP9025
1993	Honda	All - see special >	All - see special >	CP9025 manual may not list all possible trouble codes for 1993 vehicles, see vehicle service manual for complete listing & information. Check Engine Light is now referred to as the Malfunction Indicator Lamp (MIL). Service Connector locations are the same as 1992. Del Sol vehicles follow Civic instructions.	CP9025
1994	Honda	Accord	All	Requires Honda SCS Service Connector, P/N 07PAZ-0010100. See vehicle service manual for complete information & trouble code listings.	
1994	Honda	Civic	All	CP9025 manual may not list all possible trouble codes for 1994 Civics, see vehicle service manual for complete listing & information. Check Engine Light is now referred to as the Malfunction Indicator Lamp (MIL). Service Connector locations are the same as 1992.	CP9025
1994	Honda	Civic Del Sol	All	CP9025 manual may not list all possible trouble codes for 1994 Del Sol, see vehicle service manual for complete listing & information. Check Engine Light is now referred to as the Malfunction Indicator Lamp (MIL). Service Connector locations are the same as 1992. Del Sol vehicles follow Civic instructions.	CP9025
1994	Honda	Passport	All	Vehicle has self-diagnostic capabilities, vehicle service manual required. Customer supplied jumper wire required on 3.2 Liter 6 cylinder engine.	
1994	Honda	Prelude	All	CP9025 manual may not list all possible trouble codes for 1994 Preludes, see vehicle service manual for complete listing & information. Check Engine Light is now referred to as the Malfunction Indicator Lamp (MIL). Service Connector locations are the same as 1992.	CP9025
1995	Honda	Accord	2.2 L, 4 Cyl, FB22B1 2.2 L, 4 Cyl, FB22B2	Requires Honda SCS Service Connector, P/N 07PAZ-0010100. See vehicle service manual for complete information & trouble code listings.	

1995	Honda	Accord	2.7 L, 6 Cyl, C27A4	OBD II ENGINE* Can use Honda SCS Service Connector, P/N 07PAZ-0010100, if desired for historical 1 & 2 digit codes. See vehicle service manual for complete information & code listings.	CP9135, CP9145 and CP9150
1995	Honda	Civic	All	CP9025 manual may not list all possible trouble codes for 1995 Civics, see vehicle service manual for complete listing & information. Check Engine Light is now referred to as the Malfunction Indicator Lamp (MIL). Service Connector locations are the same as 1992.	CP9025
1995	Honda	Civic Del Sol	All	CP9025 manual may not list all possible trouble codes for 1995 Del Sol, see vehicle service manual for complete listing & information. Check Engine Light is now referred to as the Malfunction Indicator Lamp (MIL). Service Connector locations are the same as 1992. Del Sol vehicles follow Civic instructions.	CP9025
1995	Honda	Odyssey	All	Requires Honda SCS Service Connector, P/N 07PAZ-0010100. See vehicle service manual for complete information & trouble code listings.	
1995	Honda	Passport	All	Vehicle has self-diagnostic capabilities, vehicle service manual required. Customer supplied jumper wire required on 3.2 Liter 6 cylinder engine.	
1995	Honda	Prelude	All	CP9025 manual may not list all possible trouble codes for 1995 Preludes, see vehicle service manual for complete listing & information. Check Engine Light is now referred to as the Malfunction Indicator Lamp (MIL). Service Connector locations are the same as 1992.	CP9025

***All OBD II Engines require OBD II compliant equipment like Actron's OBD II AutoScanner CP9135, SUPER AutoScanner CP9145 or SUPER AutoScanner Kit CP9150. Beginning in 1996, all Honda vehicles were required to be OBD II compliant.**

**Nissan OBD I vehicles (1984 - 1995) supported by
Actron's Honda/Nissan/Toyota Code Scanner CP9025**

Year	Make	Model	Engine	Special	Covered By
1984	Nissan	200SX	All		CP9025
1984	Nissan	300ZX	All		CP9025
1984	Nissan	Stanza	All		CP9025
1985	Nissan	200SX	All		CP9025
1985	Nissan	300ZX	All		CP9025
1985	Nissan	Maxima	All		CP9025
1985	Nissan	Stanza	All		CP9025
1986	Nissan	200SX	All		CP9025
1986	Nissan	300ZX	All		CP9025
1986	Nissan	Maxima	All		CP9025
1986	Nissan	Stanza	All		CP9025
1986 1/2	Nissan	Pickup, California	All		CP9025
1986 1/2	Nissan	Pickup, 4WD	All		CP9025
1987	Nissan	All	All		CP9025
1988	Nissan	All	All		CP9025
1989	Nissan	All	All		CP9025
1990	Nissan	All	All		CP9025
1991	Nissan	All	All		CP9025
1992	Nissan	All	All		CP9025
1993	Nissan	All - see special >	All - see special >	<i>CP9025 manual may not list all possible trouble codes for 1993 vehicles, see vehicle service manual for complete listing & information</i>	
1993	Nissan	240SX	All	Follow manual instructions for 1992 240SX	CP9025
1993	Nissan	300ZX	All	Follow manual instructions for 1992 300ZX	CP9025
1993	Nissan	Altima	All	Follow manual instructions for 1991 Stanza	CP9025
1993	Nissan	Maxima	VG30E, VIN (H)	Follow manual instructions for 1992 Maxima with VG30E engine	CP9025
1993	Nissan	Maxima SE	VE30DE, VIN (E)	Follow manual instructions for 1992 Maxima with VE30DE engine	CP9025
1993	Nissan	NX	All	Follow manual instructions for 1992 NX	CP9025
1993	Nissan	Pathfinder	All	Follow manual instructions for 1992 Pathfinder	CP9025
1993	Nissan	Pickup	All	Follow manual instructions for 1992 Pickup	CP9025
1993	Nissan	Quest	All	Vehicle has self-diagnostic capabilities, see vehicle service manual for details & information, customer fabricated jumper wire required.	
1993	Nissan	Sentra	All	Follow manual instructions for 1992 Sentra	CP9025
1994	Nissan	All - see special >	All - see special >	<i>CP9025 manual may not list all possible trouble codes for 1994 vehicles, see vehicle service manual for complete listing & information</i>	
1994	Nissan	240SX	All	Follow manual instructions for 1992 240SX	CP9025
1994	Nissan	300ZX	All	Follow manual instructions for 1992 300ZX	CP9025
1994	Nissan	Altima	All	Follow manual instructions for 1991 Stanza	CP9025
1994	Nissan	Maxima	VG30E, VIN (H)	Follow manual instructions for 1992 Maxima with VG30E engine	CP9025
1994	Nissan	Maxima	VE30DE, VIN (E)	Follow manual instructions for 1992 Maxima with VE30DE engine	CP9025
1994	Nissan	Pathfinder	All	Follow manual instructions for 1992 Pathfinder	CP9025
1994	Nissan	Pickup	All	Follow manual instructions for 1992 Pickup	CP9025
1994	Nissan	Quest	All	Vehicle has self-diagnostic capabilities, see vehicle service manual for details & information, customer fabricated jumper wire required.	
1994	Nissan	Sentra	All	Follow manual instructions for 1992 Sentra	CP9025
1995	Nissan	All - see special >	All - see special >	<i>CP9025 manual may not list all possible trouble codes for 1995 vehicles, see vehicle service manual for complete listing & information</i>	
1995	Nissan	200SX	All	OBD II ENGINE*	CP9135, CP9145 & CP9150
1995	Nissan	240SX	All	OBD II ENGINE*	CP9135, CP9145 & CP9150
1995	Nissan	300ZX	All	Follow manual instructions for 1992 300ZX	CP9025
1995	Nissan	Altima	All	OBD II ENGINE*	CP9135, CP9145 & CP9150
1995	Nissan	Maxima	All	OBD II ENGINE*	CP9135, CP9145 & CP9150
1995	Nissan	Pathfinder	All	Follow manual instructions for 1992 Pathfinder	CP9025
1995	Nissan	Pickup	All	Follow manual instructions for 1992 Pickup	CP9025
1995	Nissan	Quest	All	Vehicle has self-diagnostic capabilities, see vehicle service manual for details & information, customer fabricated jumper wire required.	
1995	Nissan	Sentra	All	OBD II ENGINE*	CP9135, CP9145 & CP9150

***All OBD II Engines require OBD II compliant equipment like Actron's OBD II AutoScanner CP9135, SUPER AutoScanner CP9145 or SUPER AutoScanner Kit CP9150. Beginning in 1996, all Nissan vehicles were required to be OBD II compliant.**

**Toyota OBD I vehicles (1983 - 1995) supported by
Actron's Honda/Nissan/Toyota Code Scanner CP9025**

Year	Make	Model	Engine	Special	Coverage
1983	Toyota	Camry	2.0 L, 4 Cyl, 2S-E, VIN (S)		CP9025
1983	Toyota	Celica	2.4 L, 4 Cyl, 22R-E, VIN (R)		CP9025
1983	Toyota	Starlet	1.3 L, 4 Cyl, 4K-E, VIN (K)		CP9025
1984	Toyota	4Runner	2.4 L, 4 Cyl, 22R-E, VIN (R)	Covered in CP9025 manual under "Truck"	CP9025
1984	Toyota	Camry	2.0 L, 4 Cyl, 2S-E, VIN (S)		CP9025
1984	Toyota	Celica	2.4 L, 4 Cyl, 22R-E, VIN (R)		CP9025
1984	Toyota	Cressida	2.8 L, 6 Cyl, 5M-GE, VIN (M)	Has self diagnostic system, see vehicle service manual; requires special jumper wires & analog voltmeter ie. CP7605 or CP7848	
1984	Toyota	Pickup	2.4 L, 4 Cyl, 22R-E, VIN (R)	Covered in CP9025 manual under "Truck"	CP9025
1984	Toyota	Supra	2.8 L, 6 Cyl, 5M-GE, VIN (M)	Has self diagnostic system, see vehicle service manual; requires special jumper wires & analog voltmeter ie. CP7605 or CP7848	
1984	Toyota	Starlet	1.3 L, 4 Cyl, 4K-E, VIN (K)		CP9025
1984	Toyota	Van	2.0 L, 4 Cyl, 3Y-EC, VIN (Y)		CP9025
1985	Toyota	4Runner	2.4 L, 4 Cyl, 22R-E, VIN (R)		CP9025
1985	Toyota	Camry	2.0 L, 4 Cyl, 2S-E, VIN (S)		CP9025
1985	Toyota	Celica	2.4 L, 4 Cyl, 22R-E, VIN (R)		CP9025
1985	Toyota	Corolla (RWD)	1.6 L, 4 Cyl, 4A-GE, VIN (A)		CP9025
1985	Toyota	Cressida w/o super monitor option	2.8 L, 6 Cyl, 5M-GE, VIN (M)	Has self diagnostic system, see vehicle service manual; requires special jumper wires & analog voltmeter ie. CP7605 or CP7848	
1985	Toyota	Cressida w/sup mon	2.8 L, 6 Cyl, 5M-GE, VIN (M)	Has super monitor display option	CP9025
1985	Toyota	MR2	1.6 L, 4 Cyl, 4A-GE, VIN (A)		CP9025
1985	Toyota	Pickup	2.4 L, 4 Cyl, 22R-E, VIN (R)		CP9025
1985	Toyota	Supra w/o super monitor option	2.8 L, 6 Cyl, 5M-GE, VIN (M)	Has self diagnostic system, see vehicle service manual; requires special jumper wires & analog voltmeter ie. CP7605 or CP7848	
1985	Toyota	Supra w/sup mon	2.8 L, 6 Cyl, 5M-GE, VIN (M)	Has super monitor display option	CP9025
1985	Toyota	Van	2.0 L, 4 Cyl, 3Y-EC, VIN (Y)		CP9025
1986	Toyota	4Runner	2.4 L, 4 Cyl, 22R-E, VIN (R)		CP9025
1986	Toyota	4Runner	2.4 L, 4 Cyl, 22R-TE, VIN (R)		CP9025
1986	Toyota	Camry	2.0 L, 4 Cyl, 2S-E, VIN (S)		CP9025
1986	Toyota	Celica	2.0 L, 4 Cyl, 2S-E, VIN (S)		CP9025
1986	Toyota	Celica	2.0 L, 4 Cyl, 3S-GE, VIN (S)		CP9025
1986	Toyota	Corolla (RWD)	1.6 L, 4 Cyl, 4A-GE, VIN (A)		CP9025
1986	Toyota	Cressida w/o super monitor option	2.8 L, 6 Cyl, 5M-GE, VIN (M)	Has self diagnostic system, follow "TCCS-L" procedure as outlined in CP9025 manual	CP9025
1986	Toyota	Cressida w/sup mon	2.8 L, 6 Cyl, 5M-GE, VIN (M)	Has super monitor display option	CP9025
1986	Toyota	MR2	1.6 L, 4 Cyl, 4A-GE, VIN (A)		CP9025
1986	Toyota	Pickup	2.4 L, 4 Cyl, 22R-E, VIN (R)		CP9025
1986	Toyota	Pickup	2.4 L, 4 Cyl, 22R-TE, VIN (R)		CP9025
1986	Toyota	Supra w/o super monitor option	2.8 L, 6 Cyl, 5M-GE, VIN (M)	Has self diagnostic system, follow "TCCS-L" procedure as outlined in CP9025 manual	CP9025
1986	Toyota	Supra w/sup mon	2.8 L, 6 Cyl, 5M-GE, VIN (M)	Has super monitor display option	CP9025
1986	Toyota	Van	2.2 L, 4 Cyl, 4Y-EC, VIN (Y)	(If vehicle has super monitor display option, follow "TCCS-M" procedure in CP9025 manual)	CP9025
1986 1/2	Toyota	Supra w/o super monitor option	3.0 L, 6 Cyl, 7M-GE, VIN (M)	Has self diagnostic system, follow "TCCS-L" procedure as outlined in CP9025 manual	CP9025
1986 1/2	Toyota	Supra w/sup mon	3.0 L, 6 Cyl, 7M-GE, VIN (M)	Has super monitor display option	CP9025
1987	Toyota	4Runner	2.4 L, 4 Cyl, 22R-E, VIN (R)		CP9025
1987	Toyota	4Runner	2.4 L, 4 Cyl, 22R-TE, VIN (R)		CP9025
1987	Toyota	Camry	2.0 L, 4 Cyl, 3S-FE, VIN (S)		CP9025
1987	Toyota	Celica	2.0 L, 4 Cyl, 3S-FE, VIN (S)		CP9025
1987	Toyota	Celica	2.0 L, 4 Cyl, 3S-GE, VIN (S)		CP9025
1987	Toyota	Corolla, FX-16 & RWD	1.6 L, 4 Cyl, 4A-GE, VIN (A)		CP9025
1987	Toyota	Cressida	2.8 L, 6 Cyl, 5M-GE, VIN (M)	(If vehicle has super monitor display option, follow "TCCS-M" procedure in CP9025 manual)	CP9025
1987	Toyota	MR2	1.6 L, 4 Cyl, 4A-GE, VIN (A)		CP9025
1987	Toyota	Pickup	2.4 L, 4 Cyl, 22R-E, VIN (R)		CP9025
1987	Toyota	Pickup	2.4 L, 4 Cyl, 22R-TE, VIN (R)		CP9025
1987	Toyota	Supra w/o super monitor option	3.0 L, 6 Cyl, 7M-GE, VIN (M)	Has self diagnostic system, follow "TCCS-L" procedure as outlined in CP9025 manual	CP9025
1987	Toyota	Supra w/sup mon	3.0 L, 6 Cyl, 7M-GE, VIN (M)	Has super monitor display option	CP9025
1987	Toyota	Van	2.2 L, 4 Cyl, 4Y-EC, VIN (Y)		CP9025
1988	Toyota	4Runner	2.4 L, 4 Cyl, 22R, VIN (R)	California Emissions only, see vehicle service manual for complete testing details	CP9025
1988	Toyota	4Runner	2.4 L, 4 Cyl, 22R-E, VIN (R)		CP9025
1988	Toyota	4Runner	2.4 L, 4 Cyl, 22R-TE, VIN (R)		CP9025
1988	Toyota	4Runner	3.0 L, 6 Cyl, 3VZ-E, VIN (V)		CP9025

1988	Toyota	Camry	2.0 L, 4 Cyl, 3S-FE, VIN (S)		CP9025
1988	Toyota	Camry	2.5 L, 6 Cyl, 2VZ-FE, VIN (V)		CP9025
1988	Toyota	Celica	2.0 L, 4 Cyl, 3S-FE, VIN (S)		CP9025
1988	Toyota	Celica	2.0 L, 4 Cyl, 3S-GE, VIN (S)		CP9025
1988	Toyota	Celica	2.0 L, 4 Cyl, 3S-GTE, VIN (S)		CP9025
1988	Toyota	Corolla	1.6 L, 4 Cyl, 4A-F, VIN (A)	California Emissions only, see vehicle service manual for complete testing details	CP9025
1988	Toyota	Corolla	1.6 L, 4 Cyl, 4A-GE, VIN (A)		CP9025
1988	Toyota	Cressida	2.8 L, 6 Cyl, 5M-GE, VIN (M)	(If vehicle has super monitor display option, follow "TCCS-M" procedure in CP9025 manual)	CP9025
1988	Toyota	Land Cruiser	4.0 L, 6 Cyl, 3F-E, VIN (F)		CP9025
1988	Toyota	MR2	1.6 L, 4 Cyl, 4A-GE, VIN (A)		CP9025
1988	Toyota	Pickup	2.4 L, 4 Cyl, 22R, VIN (R)	California Emissions only, see vehicle service manual for complete testing details	CP9025
1988	Toyota	Pickup	2.4 L, 4 Cyl, 22R-E, VIN (R)		CP9025
1988	Toyota	Pickup	2.4 L, 4 Cyl, 22R-TE, VIN (R)		CP9025
1988	Toyota	Pickup	3.0 L, 6 Cyl, 3VZ-E, VIN (V)		CP9025
1988	Toyota	Supra w/o super monitor option	3.0 L, 6 Cyl, 7M-GE, VIN (M)	Has self diagnostic system, follow "TCCS-L" procedure as outlined in CP9025 manual	CP9025
1988	Toyota	Supra w/sup mon	3.0 L, 6 Cyl, 7M-GE, VIN (M)	Has super monitor display option	CP9025
1988	Toyota	Supra w/o super monitor option	3.0 L, 6 Cyl, 7M-GTE, VIN (M)	Has self diagnostic system, follow "TCCS-L" procedure as outlined in CP9025 manual	CP9025
1988	Toyota	Supra w/sup mon	3.0 L, 6 Cyl, 7M-GTE, VIN (M)	Has super monitor display option	CP9025
1988	Toyota	Van	2.2 L, 4 Cyl, 4Y-E, VIN (Y)		CP9025
1989	Toyota	4Runner	2.4 L, 4 Cyl, 22R-E, VIN (R)		CP9025
1989	Toyota	4Runner	3.0 L, 6 Cyl, 3VZ-E, VIN (V)		CP9025
1989	Toyota	Camry	2.0 L, 4 Cyl, 3S-FE, VIN (S)		CP9025
1989	Toyota	Camry	2.5 L, 6 Cyl, 2VZ-FE, VIN (V)		CP9025
1989	Toyota	Celica	2.0 L, 4 Cyl, 3S-FE, VIN (S)		CP9025
1989	Toyota	Celica	2.0 L, 4 Cyl, 3S-GE, VIN (S)		CP9025
1989	Toyota	Celica	2.0 L, 4 Cyl, 3S-GTE, VIN (S)		CP9025
1989	Toyota	Corolla	1.6 L, 4 Cyl, 4A-FE, VIN (A)		CP9025
1989	Toyota	Corolla	1.6 L, 4 Cyl, 4A-GE, VIN (A)		CP9025
1989	Toyota	Cressida	3.0 L, 6 Cyl, 7M-GE, VIN (M)	Diagnostic connector style & location changed, customer fabricated jumper wire required	
1989	Toyota	Land Cruiser	4.0 L, 6 Cyl, 3F-E, VIN (F)		CP9025
1989	Toyota	MR2	1.6 L, 4 Cyl, 4A-GE, VIN (A)		CP9025
1989	Toyota	Pickup	2.4 L, 4 Cyl, 22R-E, VIN (R)		CP9025
1989	Toyota	Pickup	3.0 L, 6 Cyl, 3VZ-E, VIN (V)		CP9025
1989	Toyota	Supra	3.0 L, 6 Cyl, 7M-GE, VIN (M)		CP9025
1989	Toyota	Supra	3.0 L, 6 Cyl, 7M-GTE, VIN (M)		CP9025
1989	Toyota	Van	2.2 L, 4 Cyl, 4Y-E, VIN (Y)		CP9025
1990	Toyota	4Runner	2.4 L, 4 Cyl, 22R-E, VIN (R)		CP9025
1990	Toyota	4Runner	3.0 L, 6 Cyl, 3VZ-E, VIN (V)		CP9025
1990	Toyota	Camry	2.0 L, 4 Cyl, 3S-FE, VIN (S)		CP9025
1990	Toyota	Camry	2.5 L, 6 Cyl, 2VZ-FE, VIN (V)		CP9025
1990	Toyota	Celica	1.6 L, 4 Cyl, 4A-FE, VIN (A)		CP9025
1990	Toyota	Celica	1.6 L, 4 Cyl, 4A-GE, VIN (A)		CP9025
1990	Toyota	Celica	2.0 L, 4 Cyl, 3S-GTE, VIN (S)		CP9025
1990	Toyota	Celica	2.2 L, 4 Cyl, 5S-FE, VIN (S)		CP9025
1990	Toyota	Corolla	1.6 L, 4 Cyl, 4A-FE, VIN (A)		CP9025
1990	Toyota	Corolla	1.6 L, 4 Cyl, 4A-GE, VIN (A)		CP9025
1990	Toyota	Cressida	3.0 L, 6 Cyl, 7M-GE, VIN (M)	Diagnostic connector style & location changed, customer fabricated jumper wire required	
1990	Toyota	Land Cruiser	4.0 L, 6 Cyl, 3F-E, VIN (F)		CP9025
1990	Toyota	Pickup	2.4 L, 4 Cyl, 22R-E, VIN (R)		CP9025
1990	Toyota	Pickup	3.0 L, 6 Cyl, 3VZ-E, VIN (V)		CP9025
1990	Toyota	Supra	3.0 L, 6 Cyl, 7M-GE, VIN (M)		CP9025
1990	Toyota	Supra	3.0 L, 6 Cyl, 7M-GTE, VIN (M)		CP9025
1991	Toyota	4Runner	2.4 L, 4 Cyl, 22R-E, VIN (R)		CP9025
1991	Toyota	4Runner	3.0 L, 6 Cyl, 3VZ-E, VIN (V)		CP9025
1991	Toyota	Camry	2.0 L, 4 Cyl, 3S-FE, VIN (S)		CP9025
1991	Toyota	Camry	2.5 L, 6 Cyl, 2VZ-FE, VIN (V)		CP9025
1991	Toyota	Celica	1.6 L, 4 Cyl, 4A-FE, VIN (A)		CP9025
1991	Toyota	Celica	1.6 L, 4 Cyl, 4A-GE, VIN (A)		CP9025
1991	Toyota	Celica	2.0 L, 4 Cyl, 3S-GTE, VIN (S)		CP9025
1991	Toyota	Celica	2.2 L, 4 Cyl, 5S-FE, VIN (S)		CP9025
1991	Toyota	Corolla	1.6 L, 4 Cyl, 4A-FE, VIN (A)		CP9025
1991	Toyota	Corolla	1.6 L, 4 Cyl, 4A-GE, VIN (A)		CP9025
1991	Toyota	Cressida	3.0 L, 6 Cyl, 7M-GE, VIN (M)	Diagnostic connector style & location changed, customer fabricated jumper wire required	
1991	Toyota	Land Cruiser	4.0 L, 6 Cyl, 3F-E, VIN (F)		CP9025
1991	Toyota	MR2	2.0 L, 4 Cyl, 3S-GTE, VIN (S)		CP9025
1991	Toyota	MR2	2.2 L, 4 Cyl, 5S-FE, VIN (S)		CP9025

1991	Toyota	Pickup	2.4 L, 4 Cyl, 22R-E, VIN (R)		CP9025
1991	Toyota	Pickup	3.0 L, 6 Cyl, 3VZ-E, VIN (V)		CP9025
1991	Toyota	Previa	2.4 L, 4 Cyl, 2TZ-FE, VIN (A)	Diagnostic connector located under driver's seat	CP9025
1991	Toyota	Supra	3.0 L, 6 Cyl, 7M-GE, VIN (M)		CP9025
1991	Toyota	Supra	3.0 L, 6 Cyl, 7M-GTE, VIN (M)		CP9025
1991	Toyota	Tercel	1.5 L, 4 Cyl, 3E-E, VIN (E)		CP9025
1992	Toyota	4Runner	2.4 L, 4 Cyl, 22R-E, VIN (R)		CP9025
1992	Toyota	4Runner	3.0 L, 6 Cyl, 3VZ-E, VIN (V)		CP9025
1992	Toyota	Camry	2.2 L, 4 Cyl, 5S-FE, VIN (S)	Diagnostic connector shape changed slightly, customer fabricated jumper wire may be required	CP9025
1992	Toyota	Camry	3.0 L, 6 Cyl, 3VZ-FE, VIN (V)	Diagnostic connector shape changed slightly, customer fabricated jumper wire may be required	CP9025
1992	Toyota	Celica	1.6 L, 4 Cyl, 4A-FE, VIN (A)		CP9025
1992	Toyota	Celica	1.6 L, 4 Cyl, 4A-GE, VIN (A)		CP9025
1992	Toyota	Celica	2.0 L, 4 Cyl, 3S-GTE, VIN (S)		CP9025
1992	Toyota	Celica	2.2 L, 4 Cyl, 5S-FE, VIN (S)		CP9025
1992	Toyota	Corolla	1.6 L, 4 Cyl, 4A-FE, VIN (A)		CP9025
1992	Toyota	Corolla	1.6 L, 4 Cyl, 4A-GE, VIN (A)		CP9025
1992	Toyota	Cressida	3.0 L, 6 Cyl, 7M-GE, VIN (M)	Diagnostic connector style & location changed, customer fabricated jumper wire required	CP9025
1992	Toyota	Land Cruiser	4.0 L, 6 Cyl, 3F-E, VIN (F)		CP9025
1992	Toyota	MR2	2.0 L, 4 Cyl, 3S-GTE, VIN (S)		CP9025
1992	Toyota	MR2	2.2 L, 4 Cyl, 5S-FE, VIN (S)		CP9025
1992	Toyota	Paseo	1.5 L, 4 Cyl, 5E-FE, VIN (E)		CP9025
1992	Toyota	Pickup	2.4 L, 4 Cyl, 22R-E, VIN (R)		CP9025
1992	Toyota	Pickup	3.0 L, 6 Cyl, 3VZ-E, VIN (V)		CP9025
1992	Toyota	Previa	2.4 L, 4 Cyl, 2TZ-FE, VIN (A)	Diagnostic connector located under driver's seat	CP9025
1992	Toyota	Supra	3.0 L, 6 Cyl, 7M-GE, VIN (M)		CP9025
1992	Toyota	Supra	3.0 L, 6 Cyl, 7M-GTE, VIN (M)		CP9025
1992	Toyota	Tercel	1.5 L, 4 Cyl, 3E-E, VIN (E)		CP9025
1993	Toyota	All - see special >	All - see special >	CP9025 manual may not list all possible trouble codes for 1993 vehicles, see vehicle service manual for complete listing & information	
1993	Toyota	4Runner	2.4 L, 4 Cyl, 22R-E, VIN (R)		CP9025
1993	Toyota	4Runner	3.0 L, 6 Cyl, 3VZ-E, VIN (V)	CP9025 does "Normal mode" code retrieval only, not "Test mode" code retrieval, see VSM for info.	CP9025
1993	Toyota	Camry	2.2 L, 4 Cyl, 5S-FE, VIN (S)	Diagnostic connector style & location changed, customer fabricated jumper wire required.	
1993	Toyota	Camry	3.0 L, 6 Cyl, 3VZ-FE, VIN (V)	Diagnostic connector style & location changed, customer fabricated jumper wire required.	
1993	Toyota	Celica	1.6 L, 4 Cyl, 4A-FE, VIN (A)		CP9025
1993	Toyota	Celica	1.8 L, 4 Cyl, 7A-FE, VIN (A)	CP9025 does "Normal mode" code retrieval only, not "Test mode" code retrieval, see VSM for info.	CP9025
1993	Toyota	Celica	2.0 L, 4 Cyl, 3S-GTE, VIN (S)	CP9025 does "Normal mode" code retrieval only, not "Test mode" code retrieval, see VSM for info.	CP9025
1993	Toyota	Celica	2.2 L, 4 Cyl, 5S-FE, VIN (S)	CP9025 does "Normal mode" code retrieval only, not "Test mode" code retrieval, see VSM for info.	CP9025
1993	Toyota	Corolla	1.6 L, 4 Cyl, 4A-FE, VIN (A)	Diagnostic connector style changed, customer fabricated jumper wire required.	
1993	Toyota	Corolla	1.8 L, 4 Cyl, 7A-FE, VIN (A)	Diagnostic connector style changed, customer fabricated jumper wire required.	
1993	Toyota	Land Cruiser	4.5 L, 6 Cyl, 1FZ-FE, VIN (D)	Diagnostic connector style changed, customer fabricated jumper wire required.	
1993	Toyota	MR2	2.0 L, 4 Cyl, 3S-GTE, VIN (S)	CP9025 does "Normal mode" code retrieval only, not "Test mode" code retrieval, see VSM for info.	CP9025
1993	Toyota	MR2	2.2 L, 4 Cyl, 5S-FE, VIN (S)	CP9025 does "Normal mode" code retrieval only, not "Test mode" code retrieval, see VSM for info.	CP9025
1993	Toyota	Paseo	1.5 L, 4 Cyl, 5E-FE, VIN (E)		CP9025
1993	Toyota	Pickup	2.4 L, 4 Cyl, 22R-E, VIN (R)		CP9025
1993	Toyota	Pickup	3.0 L, 6 Cyl, 3VZ-E, VIN (V)	CP9025 does "Normal mode" code retrieval only, not "Test mode" code retrieval, see VSM for info.	CP9025
1993	Toyota	Previa	2.4 L, 4 Cyl, 2TZ-FE, VIN (A)	Diagnostic connector located under driver's seat	CP9025
1993	Toyota	Supra	3.0 L, 6 Cyl, 2JZ-GE, VIN (M)	Diagnostic connector style & location changed, customer fabricated jumper wire required	
1993	Toyota	Supra	3.0 L, 6 Cyl, 2JZ-GTE, VIN (M)	Diagnostic connector style & location changed, customer fabricated jumper wire required	
1993	Toyota	T100 Pickup	3.0 L, 6 Cyl, 3VZ-E, VIN (V)	Diagnostic connector style changed, customer fabricated jumper wire required	
1993	Toyota	Tercel	1.5 L, 4 Cyl, 3E-E, VIN (E)		CP9025
1994	Toyota	All - see special >	All - see special >	CP9025 manual may not list all possible trouble codes for 1993 vehicles, see vehicle service manual for complete listing & information	
1994	Toyota	4Runner	2.4 L, 4 Cyl, 22R-E, VIN (R)		CP9025
1994	Toyota	4Runner	3.0 L, 6 Cyl, 3VZ-E, VIN (V)	CP9025 does "Normal mode" code retrieval only, not "Test mode" code retrieval, see VSM for info.	CP9025
1994	Toyota	Camry	2.2 L, 4 Cyl, 5S-FE, VIN (S)	Diagnostic connector style & location changed, customer fabricated jumper wire required	

1994	Toyota	Camry	3.0 L, 6 Cyl, 1MZ-FE, VIN (G)	OBD II ENGINE*	CP9135, CP9145 and CP9150
1994	Toyota	Celica	1.8 L, 4 Cyl, 7A-FE, VIN (A)	Diagnostic connector style changed, customer fabricated jumper wire required	
1994	Toyota	Celica	2.2 L, 4 Cyl, 5S-FE, VIN (S)	Diagnostic connector style changed, customer fabricated jumper wire required	
1994	Toyota	Corolla	1.6 L, 4 Cyl, 4A-FE, VIN (A)	Diagnostic connector style changed, customer fabricated jumper wire required	
1994	Toyota	Corolla	1.8 L, 4 Cyl, 7A-FE, VIN (A)	Diagnostic connector style changed, customer fabricated jumper wire required	
1994	Toyota	Land Cruiser	4.5 L, 6 Cyl, 1FZ-FE, VIN (D)	Diagnostic connector style changed, customer fabricated jumper wire required	
1994	Toyota	MR2	2.0 L, 4 Cyl, 3S-GTE, VIN (S)	CP9025 does "Normal mode" code retrieval only, not "Test mode" code retrieval, see VSM for info.	CP9025
1994	Toyota	MR2	2.2 L, 4 Cyl, 5S-FE, VIN (S)	CP9025 does "Normal mode" code retrieval only, not "Test mode" code retrieval, see VSM for info.	CP9025
1994	Toyota	Paseo	1.5 L, 4 Cyl, 5E-FE, VIN (E)		CP9025
1994	Toyota	Pickup	2.4 L, 4 Cyl, 22R-E, VIN (R)		CP9025
1994	Toyota	Pickup	3.0 L, 6 Cyl, 3VZ-E, VIN (V)	CP9025 does "Normal mode" code retrieval only, not "Test mode" code retrieval, see VSM for info.	CP9025
1994	Toyota	Previa	2.4 L, 4 Cyl, 2TZ-FE, VIN (A)	Diagnostic connector located under driver's seat. CP9025 does "Normal mode" code retrieval only, not "Test mode" code retrieval, see VSM for info.	CP9025
1994	Toyota	Previa	2.4 L, 4 Cyl, 2TZ-FZE, VIN (A)	OBD II ENGINE*	CP9135, CP9145 and CP9150
1994	Toyota	Supra	3.0 L, 6 Cyl, 2JZ-GE, VIN (J)	Diagnostic connector style & location changed, customer fabricated jumper wire required	
1994	Toyota	Supra	3.0 L, 6 Cyl, 2JZ-GTE, VIN (J)	Diagnostic connector style & location changed, customer fabricated jumper wire required	
1994	Toyota	T100 Pickup	2.7 L, 4 Cyl, 3RZ-FE, VIN (U)	OBD II ENGINE*	CP9135, CP9145 and CP9150
1994	Toyota	T100 Pickup	3.0 L, 6 Cyl, 3VZ-E, VIN (V)	Diagnostic connector style changed, customer fabricated jumper wire required	
1994	Toyota	Tercel	1.5 L, 4 Cyl, 3E-E, VIN (E)		CP9025
1995	Toyota	All - see special >	All - see special >	CP9025 manual may not list all possible trouble codes for 1993 vehicles, see vehicle service manual for complete listing & information	
1995	Toyota	4Runner	2.4 L, 4 Cyl, 22R-E, VIN (R)		CP9025
1995	Toyota	4Runner	3.0 L, 6 Cyl, 3VZ-E, VIN (V)	CP9025 does "Normal mode" code retrieval only, not "Test mode" code retrieval, see VSM for info.	CP9025
1995	Toyota	Avalon	3.0 L, 6 Cyl, 1MZ-FE, VIN (G)	OBD II ENGINE*	CP9135, CP9145 and CP9150
1995	Toyota	Camry	2.2 L, 4 Cyl, 5S-FE, VIN (S)	Diagnostic connector style changed, customer fabricated jumper wire required	
1995	Toyota	Camry	3.0 L, 6 Cyl, 1MZ-FE, VIN (G)	OBD II ENGINE*	CP9135, CP9145 and CP9150
1995	Toyota	Celica	1.8 L, 4 Cyl, 7A-FE, VIN (A)	Diagnostic connector style changed, customer fabricated jumper wire required	
1995	Toyota	Celica	2.2 L, 4 Cyl, 5S-FE, VIN (S)	Diagnostic connector style changed, customer fabricated jumper wire required	
1995	Toyota	Corolla	1.6 L, 4 Cyl, 4A-FE, VIN (A)	Diagnostic connector style changed, customer fabricated jumper wire required	
1995	Toyota	Corolla	1.8 L, 4 Cyl, 7A-FE, VIN (A)	Diagnostic connector style changed, customer fabricated jumper wire required	
1995	Toyota	Land Cruiser	4.5 L, 6 Cyl, 1FZ-FE, VIN (D)	OBD II ENGINE*	CP9135, CP9145 and CP9150
1995	Toyota	MR2	2.0 L, 4 Cyl, 3S-GTE, VIN (S)	Diagnostic connector style changed, customer fabricated jumper wire required	
1995	Toyota	MR2	2.2 L, 4 Cyl, 5S-FE, VIN (S)	CP9025 does "Normal mode" code retrieval only, not "Test mode" code retrieval, see VSM for info.	CP9025
1995	Toyota	Paseo	1.5 L, 4 Cyl, 5E-FE, VIN (E)	Diagnostic connector style changed, customer fabricated jumper wire required	
1995	Toyota	Pickup	2.4 L, 4 Cyl, 22R-E, VIN (R)		CP9025
1995	Toyota	Pickup	3.0 L, 6 Cyl, 3VZ-E, VIN (V)	CP9025 does "Normal mode" code retrieval only, not "Test mode" code retrieval, see VSM for info.	CP9025
1995	Toyota	Previa	2.4 L, 4 Cyl, 2TZ-FE, VIN (A)	Diagnostic connector style changed, not "Test mode" code retrieval, see VSM for info.	
1995	Toyota	Previa	2.4 L, 4 Cyl, 2TZ-FZE, VIN (A)	OBD II ENGINE*	CP9135, CP9145 and CP9150
1995	Toyota	Supra	3.0 L, 6 Cyl, 2JZ-GE, VIN (J)	Diagnostic connector style & location changed, customer fabricated jumper wire required	
1995	Toyota	Supra	3.0 L, 6 Cyl, 2JZ-GTE, VIN (J)	Diagnostic connector style & location changed, customer fabricated jumper wire required	
1995	Toyota	T100 Pickup	2.7 L, 4 Cyl, 3RZ-FE, VIN (U)	OBD II ENGINE*	CP9135, CP9145 and CP9150
1995	Toyota	T100 Pickup	3.4 L, 6 Cyl, 5VZ-FE, VIN (V)	OBD II ENGINE*	CP9135, CP9145 and CP9150
1995	Toyota	Tacoma	2.4 L, 4 Cyl, 2RZ-FE, VIN (U)	OBD II ENGINE*	CP9135, CP9145 and CP9150

1995	Toyota	Tacoma	2.7 L, 4 Cyl, 3RZ-FE, VIN (U)	OBD II ENGINE*	CP9135, CP9145 and CP9150
1995	Toyota	Tacoma	3.4 L, 6 Cyl, 5VZ-FE, VIN (V)	OBD II ENGINE*	CP9135, CP9145 and CP9150
1995	Toyota	Tercel	1.5 L, 4 Cyl, 3E-E, VIN (E)	OBD II ENGINE*	CP9135, CP9145 and CP9150

***All OBD II Engines require OBD II compliant equipment like Actron's OBD II AutoScanner CP9135, SUPER AutoScanner CP9145 or SUPER AutoScanner Kit CP9150. Beginning in 1996, all Honda vehicles were required to be OBD II compliant.**